

# WT20 Quick Installation Guide (QIG)

WirelessTouch collaboration solution


## Package




Host  
x 1




Dongle  
x 1



Micro-USB to  
USB-A cable x 1



USB-A to  
USB-B cable x 1




Mounting plate  
Receiver x 1






Mounting plate  
Transmitter x 1

## Set up


### Step 1: Connect Host with touch display



1. Connect touch cable to host: USB-A (Host) to USB-B (Display)
2. Connect Power cable to display: MicroUSB (Host) to USB-A (Display)




Stick metal plate on back side display,  
Host can magnetic on it.



Stick metal plate on front side display,  
Host can magnetic on it.


### Step 2: Connect Dongle into laptop




Connect USB dongle into laptop

## Pairing & Connect

### Pairing Mode



Long press button for 3 seconds



Long press button for 3 seconds


Pairing Mode  
Long Press 3 Sec.

Flashing  
BLUE


Static  
GREEN

Paired  
Ready to touch

### Connect & Touch



1. Plug & Touch: Free software/driver installation
2. Windows system support up to 10 points touch; MAC system support 1 point touch
3. Support up to 4K resolution and extended mode



4K

